

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-8/7/06	040616475-0001	Southwest Area (sidewalk bridge level)	8/7/06	3.56	Silica	NIOSH 7500 XRD	EMSL	8/8/06	< 1	No	No	
SILICA-ST2-8/7/06	040616475-0002	Southeast Area (sidewalk bridge level)	8/7/06	3.63	Silica	NIOSH 7500 XRD	EMSL	8/8/06	< 1	No	No	
SILICA-ST4-8/7/06	040616475-0003	Northwest Area (street-level)	8/7/06	3.65	Silica	NIOSH 7500 XRD	EMSL	8/8/06	< 1	No	No	
SILICA-ST5-8/7/06	040616475-0004	Firehouse #10 (roof level)	8/7/06	3.59	Silica	NIOSH 7500 XRD	EMSL	8/8/06	< 1	No	No	
SILICA-ST6-8/7/06	040616476-0001	Southwest Area (roof level)	8/7/06	3.7	Silica	NIOSH 7500 XRD	EMSL	8/8/06	< 1	No	No	
SILICA-ST7-8/7/06	040616476-0002	Southeast Area (roof level)	8/7/06	3.59	Silica	NIOSH 7500 XRD	EMSL	8/8/06	< 1	No	No	
SILICA-ST8-8/7/06	040616476-0003	Northeast Area (roof level)	8/7/06	3.66	Silica	NIOSH 7500 XRD	EMSL	8/8/06	< 1	No	No	
SILICA-ST9-8/7/06	040616476-0004	Northwest Area (roof level)	8/7/06	3.68	Silica	NIOSH 7500 XRD	EMSL	8/8/06	< 1	No	No	
SILICA-ST10-8/7/06	040616475-0005	North Side Sidewalk Bridge	8/7/06	3.58	Silica	NIOSH 7500 XRD	EMSL	8/8/06	< 1	No	No	
SILICA-ST11-8/7/06	040616475-0006	90 Trinity Place (roof level)	8/7/06	3.57	Silica	NIOSH 7500 XRD	EMSL	8/8/06	< 1	No	No	
SILICA-ST12-8/7/06	040616475-0007	110 Greenwich Street (roof level)	8/7/06	3.68	Silica	NIOSH 7500 XRD	EMSL	8/8/06	< 1	No	No	
SILICA-ST13-8/7/06	040616475-0008	Marriott Hotel, 38th Floor (roof level)	8/7/06	3.56	Silica	NIOSH 7500 XRD	EMSL	8/8/06	< 1	No	No	
SILICA-ST14-8/7/06	040616475-0009	West Face - South end at corner (scaffolding level)	8/7/06	3.6	Silica	NIOSH 7500 XRD	EMSL	8/8/06	< 1	No	No	
SILICA-ST15-8/7/06	040616475-0010	South Face - East end at corner (scaffolding level)	8/7/06	3.57	Silica	NIOSH 7500 XRD	EMSL	8/8/06	< 1	No	No	
SILICA-ST16-8/7/06	040616475-0011	East Face - North end at corner (scaffolding level)	8/7/06	3.67	Silica	NIOSH 7500 XRD	EMSL	8/8/06	< 1	No	No	
SILICA-ST17-8/7/06	040616475-0012	North Face - West end at corner (scaffolding level)	8/7/06	3.61	Silica	NIOSH 7500 XRD	EMSL	8/8/06	< 1	No	No	