

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST4-8/23/07	040720964-0001	Northwest Area (street-level)	8/23/07	3.52	Silica	NIOSH 7500 XRD	EMSL	8/24/07	< 1	No	No	
SILICA-ST5-8/23/07	040720964-0002	Firehouse #10 (roof level)	8/23/07	3.56	Silica	NIOSH 7500 XRD	EMSL	8/24/07	< 1	No	No	
SILICA-ST10-8/23/07	040720964-0003	North Side Sidewalk Bridge	8/23/07	3.54	Silica	NIOSH 7500 XRD	EMSL	8/24/07	< 1	No	No	
SILICA-ST11-8/23/07	040720964-0004	90 Trinity Place (roof level)	8/23/07	3.49	Silica	NIOSH 7500 XRD	EMSL	8/24/07	< 1	No	No	
SILICA-ST12-8/23/07	040720964-0005	110 Greenwich Street (roof level)	8/23/07	3.69	Silica	NIOSH 7500 XRD	EMSL	8/24/07	< 1	No	No	
SILICA-ST13-8/23/07	040720964-0006	Marriott Hotel, 38th Floor (roof level)	8/23/07	3.54	Silica	NIOSH 7500 XRD	EMSL	8/24/07	< 1	No	No	
SILICA-ST4-8/24/07	040721322-0001	Northwest Area (street-level)	8/24/07	11.99	Silica	NIOSH 7500 XRD	EMSL	8/28/07	< 0.4	No	No	Result represents conditions from 8/24/07 through 8/28/07
SILICA-ST5-8/24/07	040721078-0001	Firehouse #10 (roof level)	8/24/07	3.48	Silica	NIOSH 7500 XRD	EMSL	8/25/07	< 1	No	No	
SILICA-ST10-8/24/07	040721078-0002	North Side Sidewalk Bridge	8/24/07	3.57	Silica	NIOSH 7500 XRD	EMSL	8/25/07	< 1	No	No	
SILICA-ST100-8/24/07	040721078-0006	Station 10 Field Duplicate	8/24/07	3.61	Silica	NIOSH 7500 XRD	EMSL	8/25/07	< 1	No	No	
SILICA-ST11-8/24/07	040721078-0003	90 Trinity Place (roof level)	8/24/07	3.52	Silica	NIOSH 7500 XRD	EMSL	8/25/07	< 1	No	No	
SILICA-ST12-8/24/07	040721078-0004	110 Greenwich Street (roof level)	8/24/07	3.57	Silica	NIOSH 7500 XRD	EMSL	8/25/07	< 1	No	No	
SILICA-ST13-8/24/07	040721078-0005	Marriott Hotel, 38th Floor (roof level)	8/24/07	3.51	Silica	NIOSH 7500 XRD	EMSL	8/25/07	< 1	No	No	
SILICA-ST5-8/25/07	040721077-0001	Firehouse #10 (roof level)	8/25/07	3.55	Silica	NIOSH 7500 XRD	EMSL	8/26/07	< 1	No	No	
SILICA-ST10-8/25/07	040721077-0002	North Side Sidewalk Bridge	8/25/07	3.45	Silica	NIOSH 7500 XRD	EMSL	8/26/07	< 1	No	No	
SILICA-ST11-8/25/07	040721151-0007	90 Trinity Place (roof level)	8/25/07	3.5	Silica	NIOSH 7500 XRD	EMSL	8/28/07	< 1	No	No	
SILICA-ST12-8/25/07	040721077-0003	110 Greenwich Street (roof level)	8/25/07	3.5	Silica	NIOSH 7500 XRD	EMSL	8/26/07	< 1	No	No	
SILICA-ST13-8/25/07	040721077-0004	Marriott Hotel, 38th Floor (roof level)	8/25/07	3.53	Silica	NIOSH 7500 XRD	EMSL	8/26/07	< 1	No	No	

Note:

1. Silica samples at Station 1 (Southwest Area [sidewalk bridge level]) and Station 2 (Southeast Area [sidewalk bridge level]) on August 23 through 25, 2007 were not collected. The stations were not accessible on account of a fire at 130 Liberty Street that caused unsafe conditions in the vicinity of the stations.
2. Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]) and Station 17 (North Face - West end at corner [scaffolding level]) were not collected on August 23 through 25, 2007. The stations were not accessible on account of a fire at 130 Liberty Street.
3. Silica samples at Station 4 (Northwest Area [street-level]) on August 25, 2007 was not collected. The station was not accessible on account of a fire at 130 Liberty Street that caused unsafe conditions in the vicinity of the stations.