

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									10			
SILICA-ST1-10/3/06	040621109-0001	Southwest Area (sidewalk bridge level)	10/3/06	3.8	Silica	NIOSH 7500 XRD	EMSL	10/4/06	< 1	No	No	
SILICA-ST2-10/3/06	040621109-0002	Southeast Area (sidewalk bridge level)	10/3/06	3.59	Silica	NIOSH 7500 XRD	EMSL	10/4/06	< 1	No	No	
SILICA-ST4-10/3/06	040621109-0003	Northwest Area (street-level)	10/3/06	3.7	Silica	NIOSH 7500 XRD	EMSL	10/4/06	< 1	No	No	
SILICA-ST5-10/3/06	040621109-0004	Firehouse #10 (roof level)	10/3/06	3.53	Silica	NIOSH 7500 XRD	EMSL	10/4/06	< 1	No	No	
SILICA-ST10-10/3/06	040621109-0005	North Side Sidewalk Bridge	10/3/06	3.63	Silica	NIOSH 7500 XRD	EMSL	10/4/06	< 1	No	No	
SILICA-ST11-10/3/06	040621109-0006	90 Trinity Place (roof level)	10/3/06	3.56	Silica	NIOSH 7500 XRD	EMSL	10/4/06	< 1	No	No	
SILICA-ST12-10/3/06	040621109-0007	110 Greenwich Street (roof level)	10/3/06	3.55	Silica	NIOSH 7500 XRD	EMSL	10/4/06	< 1	No	No	
SILICA-ST13-10/3/06	040621109-0008	Marriott Hotel, 38th Floor (roof level)	10/3/06	3.53	Silica	NIOSH 7500 XRD	EMSL	10/4/06	< 1	No	No	
SILICA-ST14-10/3/06	040621109-0009	West Face - South end at corner (scaffolding level)	10/3/06	3.7	Silica	NIOSH 7500 XRD	EMSL	10/4/06	< 1	No	No	
SILICA-ST15-10/3/06	040621109-0010	South Face - East end at corner (scaffolding level)	10/3/06	3.67	Silica	NIOSH 7500 XRD	EMSL	10/4/06	< 1	No	No	
SILICA-ST16-10/3/06	040621109-0011	East Face - North end at corner (scaffolding level)	10/3/06	3.68	Silica	NIOSH 7500 XRD	EMSL	10/4/06	< 1	No	No	
SILICA-ST17-10/3/06	040621109-0012	North Face - West end at corner (scaffolding level)	10/3/06	3.69	Silica	NIOSH 7500 XRD	EMSL	10/4/06	< 1	No	No	