

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									10	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
									10			
SILICA-ST1-10/3/08	040825882-0001	Southwest Area (sidewalk bridge level)	10/3/08	3.68	Silica	NIOSH 7500 XRD	EMSL	10/4/08	< 1	No	No	
SILICA-ST2-10/3/08	040825882-0002	Southeast Area (sidewalk bridge level)	10/3/08	3.69	Silica	NIOSH 7500 XRD	EMSL	10/4/08	< 1	No	No	
SILICA-ST4-10/3/08	040825882-0003	Northwest Area (street-level)	10/3/08	3.68	Silica	NIOSH 7500 XRD	EMSL	10/4/08	1	No	No	
SILICA-ST5-10/3/08	040825882-0004	Firehouse #10 (roof level)	10/3/08	3.56	Silica	NIOSH 7500 XRD	EMSL	10/4/08	< 1	No	No	
SILICA-ST10-10/3/08	040825882-0005	North Side Sidewalk Bridge	10/3/08	3.61	Silica	NIOSH 7500 XRD	EMSL	10/4/08	< 1	No	No	
SILICA-ST11-10/3/08	040825882-0006	90 Trinity Place (roof level)	10/3/08	3.57	Silica	NIOSH 7500 XRD	EMSL	10/4/08	3	No	No	
SILICA-ST12-10/3/08	040825882-0007	110 Greenwich Street (roof level)	10/3/08	3.53	Silica	NIOSH 7500 XRD	EMSL	10/4/08	< 1	No	No	
SILICA-ST13-10/3/08	040825882-0008	Marriott Hotel, 38th Floor (roof level)	10/3/08	3.6	Silica	NIOSH 7500 XRD	EMSL	10/4/08	< 1	No	No	
SILICA-ST14 15th Flr -10/3/08	040825882-0009	West Face - South end at corner (scaffolding level: 15th floor)	10/3/08	3.41	Silica	NIOSH 7500 XRD	EMSL	10/4/08	< 1	No	No	
SILICA-ST15 15th Flr -10/3/08	040825882-0010	South Face - East end at corner (scaffolding level: 15th floor)	10/3/08	3.39	Silica	NIOSH 7500 XRD	EMSL	10/4/08	< 1	No	No	
SILICA-ST16 15th Flr -10/3/08	040825882-0011	East Face - North end at corner (scaffolding level: 15th floor)	10/3/08	3.43	Silica	NIOSH 7500 XRD	EMSL	10/4/08	< 1	No	No	
SILICA-ST17 15th Flr -10/3/08	040825882-0012	North Face - West end at corner (scaffolding level: 15th floor)	10/3/08	3.44	Silica	NIOSH 7500 XRD	EMSL	10/4/08	< 1	No	No	