

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-10/18/06	040622303-0001	Southwest Area (sidewalk bridge level)	10/18/06	3.61	Silica	NIOSH 7500 XRD	EMSL	10/19/06	< 1	No	No	
SILICA-ST2-10/18/06	040622303-0002	Southeast Area (sidewalk bridge level)	10/18/06	3.65	Silica	NIOSH 7500 XRD	EMSL	10/19/06	< 1	No	No	
SILICA-ST4-10/18/06	040622303-0003	Northwest Area (street-level)	10/18/06	3.69	Silica	NIOSH 7500 XRD	EMSL	10/19/06	< 1	No	No	
SILICA-ST5-10/18/06	040622303-0004	Firehouse #10 (roof level)	10/18/06	3.78	Silica	NIOSH 7500 XRD	EMSL	10/19/06	< 1	No	No	
SILICA-ST10-10/18/06	040622303-0005	North Side Sidewalk Bridge	10/18/06	3.69	Silica	NIOSH 7500 XRD	EMSL	10/19/06	< 1	No	No	
SILICA-ST11-10/18/06	040622303-0006	90 Trinity Place (roof level)	10/18/06	3.59	Silica	NIOSH 7500 XRD	EMSL	10/19/06	< 1	No	No	
SILICA-ST12-10/18/06	040622303-0007	110 Greenwich Street (roof level)	10/18/06	3.59	Silica	NIOSH 7500 XRD	EMSL	10/19/06	< 1	No	No	
SILICA-ST13-10/18/06	040622303-0008	Marriott Hotel, 38th Floor (roof level)	10/18/06	3.61	Silica	NIOSH 7500 XRD	EMSL	10/19/06	< 1	No	No	
SILICA-ST14-10/18/06	040622303-0009	West Face - South end at corner (scaffolding level)	10/18/06	3.72	Silica	NIOSH 7500 XRD	EMSL	10/19/06	< 1	No	No	
SILICA-ST15-10/18/06	040622303-0010	South Face - East end at corner (scaffolding level)	10/18/06	3.71	Silica	NIOSH 7500 XRD	EMSL	10/19/06	< 1	No	No	
SILICA-ST16-10/18/06	040622303-0011	East Face - North end at corner (scaffolding level)	10/18/06	3.62	Silica	NIOSH 7500 XRD	EMSL	10/19/06	< 1	No	No	
SILICA-ST17-10/18/06	040622303-0012	North Face - West end at corner (scaffolding level)	10/18/06	3.72	Silica	NIOSH 7500 XRD	EMSL	10/19/06	< 1	No	No	
SILICA-ST1-10/19/06	040622375-0001	Southwest Area (sidewalk bridge level)	10/19/06	3.58	Silica	NIOSH 7500 XRD	EMSL	10/20/06	< 1	No	No	
SILICA-ST2-10/19/06	040622375-0002	Southeast Area (sidewalk bridge level)	10/19/06	3.51	Silica	NIOSH 7500 XRD	EMSL	10/20/06	< 1	No	No	
SILICA-ST4-10/19/06	040622375-0003	Northwest Area (street-level)	10/19/06	3.57	Silica	NIOSH 7500 XRD	EMSL	10/20/06	< 1	No	No	
SILICA-ST5-10/19/06	040622375-0004	Firehouse #10 (roof level)	10/19/06	3.47	Silica	NIOSH 7500 XRD	EMSL	10/20/06	< 1	No	No	
SILICA-ST10-10/19/06	040622375-0005	North Side Sidewalk Bridge	10/19/06	3.55	Silica	NIOSH 7500 XRD	EMSL	10/20/06	< 1	No	No	
SILICA-ST11-10/19/06	040622375-0006	90 Trinity Place (roof level)	10/19/06	3.61	Silica	NIOSH 7500 XRD	EMSL	10/20/06	< 1	No	No	
SILICA-ST12-10/19/06	040622375-0007	110 Greenwich Street (roof level)	10/19/06	3.6	Silica	NIOSH 7500 XRD	EMSL	10/20/06	< 1	No	No	
SILICA-ST13-10/19/06	040622375-0008	Marriott Hotel, 38th Floor (roof level)	10/19/06	3.57	Silica	NIOSH 7500 XRD	EMSL	10/20/06	< 1	No	No	
SILICA-ST14-10/19/06	040622375-0009	West Face - South end at corner (scaffolding level)	10/19/06	3.54	Silica	NIOSH 7500 XRD	EMSL	10/20/06	< 1	No	No	
SILICA-ST15-10/19/06	040622375-0010	South Face - East end at corner (scaffolding level)	10/19/06	3.52	Silica	NIOSH 7500 XRD	EMSL	10/20/06	< 1	No	No	
SILICA-ST16-10/19/06	040622375-0011	East Face - North end at corner (scaffolding level)	10/19/06	3.6	Silica	NIOSH 7500 XRD	EMSL	10/20/06	< 1	No	No	
SILICA-ST17-10/19/06	040622375-0012	North Face - West end at corner (scaffolding level)	10/19/06	3.49	Silica	NIOSH 7500 XRD	EMSL	10/20/06	< 1	No	No	