

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									10			
SILICA-ST1-11/6/06	040623823-0001	Southwest Area (sidewalk bridge level)	11/6/06	3.59	Silica	NIOSH 7500 XRD	EMSL	11/7/06	< 1	No	No	
SILICA-ST2-11/6/06	040623823-0002	Southeast Area (sidewalk bridge level)	11/6/06	3.58	Silica	NIOSH 7500 XRD	EMSL	11/7/06	< 1	No	No	
SILICA-ST4-11/6/06	040623823-0003	Northwest Area (street-level)	11/6/06	3.58	Silica	NIOSH 7500 XRD	EMSL	11/7/06	< 1	No	No	
SILICA-ST5-11/6/06	040623823-0004	Firehouse #10 (roof level)	11/6/06	3.34	Silica	NIOSH 7500 XRD	EMSL	11/7/06	< 1	No	No	
SILICA-ST10-11/6/06	040623823-0005	North Side Sidewalk Bridge	11/6/06	3.59	Silica	NIOSH 7500 XRD	EMSL	11/7/06	< 1	No	No	
SILICA-ST11-11/6/06	040623823-0006	90 Trinity Place (roof level)	11/6/06	3.52	Silica	NIOSH 7500 XRD	EMSL	11/7/06	< 1	No	No	
SILICA-ST12-11/6/06	040623823-0007	110 Greenwich Street (roof level)	11/6/06	3.61	Silica	NIOSH 7500 XRD	EMSL	11/7/06	< 1	No	No	
SILICA-ST13-11/6/06	040623823-0008	Marriott Hotel, 38th Floor (roof level)	11/6/06	3.65	Silica	NIOSH 7500 XRD	EMSL	11/7/06	< 1	No	No	
SILICA-ST14-11/6/06	040623823-0009	West Face - South end at corner (scaffolding level)	11/6/06	3.47	Silica	NIOSH 7500 XRD	EMSL	11/7/06	< 1	No	No	
SILICA-ST15-11/6/06	040623823-0010	South Face - East end at corner (scaffolding level)	11/6/06	3.2	Silica	NIOSH 7500 XRD	EMSL	11/7/06	< 2	No	No	
SILICA-ST16-11/6/06	040623823-0011	East Face - North end at corner (scaffolding level)	11/6/06	3.55	Silica	NIOSH 7500 XRD	EMSL	11/7/06	< 1	No	No	
SILICA-ST17-11/6/06	040623823-0012	North Face - West end at corner (scaffolding level)	11/6/06	3.61	Silica	NIOSH 7500 XRD	EMSL	11/7/06	< 1	No	No	