

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									10	Air Quality Levels	Site Specific Trigger Levels	
									10			
SILICA-ST1-11/17/08	040829665-0001	Southwest Area (sidewalk bridge level)	11/17/08	3.65	Silica	NIOSH 7500 XRD	EMSL	11/18/08	< 1	No	No	
SILICA-ST2-11/17/08	040829665-0002	Southeast Area (sidewalk bridge level)	11/17/08	3.61	Silica	NIOSH 7500 XRD	EMSL	11/18/08	< 1	No	No	
SILICA-ST4-11/17/08	040829665-0003	Northwest Area (street-level)	11/17/08	3.68	Silica	NIOSH 7500 XRD	EMSL	11/18/08	< 1	No	No	
SILICA-ST5-11/17/08	040829665-0004	Firehouse #10 (roof level)	11/17/08	3.59	Silica	NIOSH 7500 XRD	EMSL	11/18/08	< 1	No	No	
SILICA-ST10-11/17/08	040829665-0005	North Side Sidewalk Bridge	11/17/08	3.73	Silica	NIOSH 7500 XRD	EMSL	11/18/08	2	No	No	
SILICA-ST11-11/17/08	040829665-0006	90 Trinity Place (roof level)	11/17/08	3.62	Silica	NIOSH 7500 XRD	EMSL	11/18/08	< 1	No	No	
SILICA-ST12-11/17/08	040829665-0007	110 Greenwich Street (roof level)	11/17/08	3.62	Silica	NIOSH 7500 XRD	EMSL	11/18/08	< 1	No	No	
SILICA-ST13-11/17/08	040829665-0008	Marriott Hotel, 38th Floor (roof level)	11/17/08	3.65	Silica	NIOSH 7500 XRD	EMSL	11/18/08	< 1	No	No	
SILICA-ST14 15th Flr -11/17/08	040829665-0009	West Face - South end at corner (scaffolding level: 15th floor)	11/17/08	3.53	Silica	NIOSH 7500 XRD	EMSL	11/18/08	< 1	No	No	
SILICA-ST15 15th Flr -11/17/08	040829665-0010	South Face - East end at corner (scaffolding level: 15th floor)	11/17/08	3.53	Silica	NIOSH 7500 XRD	EMSL	11/18/08	< 1	No	No	
SILICA-ST16 15th Flr -11/17/08	040829665-0011	East Face - North end at corner (scaffolding level: 15th floor)	11/17/08	3.54	Silica	NIOSH 7500 XRD	EMSL	11/18/08	< 1	No	No	
SILICA-ST17 15th Flr -11/17/08	040829665-0012	North Face - West end at corner (scaffolding level: 15th floor)	11/17/08	3.6	Silica	NIOSH 7500 XRD	EMSL	11/18/08	< 1	No	No	