

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									10			
EPA Site Specific Trigger Levels									10			
SILICA-ST1-11/30/10	041027754-0001	Southwest Area (sidewalk bridge level)	11/30/10	3.64	Silica	NIOSH 7500 XRD	EMSL	12/2/10	< 1	No	No	
SILICA-ST2-11/30/10	041027754-0002	Southeast Area (sidewalk bridge level)	11/30/10	3.44	Silica	NIOSH 7500 XRD	EMSL	12/2/10	< 1	No	No	
SILICA-ST4-11/30/10	041027754-0003	Northwest Area (street-level)	11/30/10	3.66	Silica	NIOSH 7500 XRD	EMSL	12/2/10	< 1	No	No	
SILICA-ST20-11/30/10	041027754-0004	Northeast Area, Sidewalk Bridge	11/30/10	3.59	Silica	NIOSH 7500 XRD	EMSL	12/2/10	< 1	No	No	