

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-12/03/06	040625697-0001	Southwest Area (sidewalk bridge level)	12/3/06	3.7	Silica	NIOSH 7500 XRD	EMSL	12/4/06	< 1	No	No	
SILICA-ST4-12/03/06	040625697-0002	Northwest Area (street-level)	12/3/06	3.75	Silica	NIOSH 7500 XRD	EMSL	12/4/06	< 1	No	No	
SILICA-ST5-12/03/06	040625697-0003	Firehouse #10 (roof level)	12/3/06	3.49	Silica	NIOSH 7500 XRD	EMSL	12/4/06	< 1	No	No	
SILICA-ST10-12/03/06	040625697-0004	North Side Sidewalk Bridge	12/3/06	3.58	Silica	NIOSH 7500 XRD	EMSL	12/4/06	< 1	No	No	
SILICA-ST11-12/03/06	040625697-0005	90 Trinity Place (roof level)	12/3/06	3.49	Silica	NIOSH 7500 XRD	EMSL	12/4/06	< 1	No	No	
SILICA-ST12-12/03/06	040625697-0006	110 Greenwich Street (roof level)	12/3/06	3.72	Silica	NIOSH 7500 XRD	EMSL	12/4/06	< 1	No	No	
SILICA-ST13-12/03/06	040625697-0007	Marriott Hotel, 38th Floor (roof level)	12/3/06	3.71	Silica	NIOSH 7500 XRD	EMSL	12/4/06	< 1	No	No	
SILICA-ST14-12/03/06	040625697-0008	West Face - South end at corner (scaffolding level)	12/3/06	4.02	Silica	NIOSH 7500 XRD	EMSL	12/4/06	< 1	No	No	
SILICA-ST15-12/03/06	040625697-0009	South Face - East end at corner (scaffolding level)	12/3/06	3.95	Silica	NIOSH 7500 XRD	EMSL	12/4/06	< 1	No	No	
SILICA-ST16-12/03/06	040625697-0010	East Face - North end at corner (scaffolding level)	12/3/06	3.97	Silica	NIOSH 7500 XRD	EMSL	12/4/06	< 1	No	No	
SILICA-ST17-12/03/06	040625697-0011	North Face - West end at corner (scaffolding level)	12/3/06	4.12	Silica	NIOSH 7500 XRD	EMSL	12/4/06	< 1	No	No	
SILICA-ST1-12/04/06	040625770-0001	Southwest Area (sidewalk bridge level)	12/4/06	3.53	Silica	NIOSH 7500 XRD	EMSL	12/5/06	< 1	No	No	
SILICA-ST2-12/04/06	040625770-0002	Southeast Area (sidewalk bridge level)	12/4/06	3.8	Silica	NIOSH 7500 XRD	EMSL	12/5/06	< 1	No	No	
SILICA-ST4-12/04/06	040625770-0003	Northwest Area (street-level)	12/4/06	3.78	Silica	NIOSH 7500 XRD	EMSL	12/5/06	< 1	No	No	
SILICA-ST5-12/04/06	040625770-0004	Firehouse #10 (roof level)	12/4/06	3.6	Silica	NIOSH 7500 XRD	EMSL	12/5/06	< 1	No	No	
SILICA-ST10-12/04/06	040625770-0005	North Side Sidewalk Bridge	12/4/06	3.61	Silica	NIOSH 7500 XRD	EMSL	12/5/06	< 1	No	No	
SILICA-ST100-12/04/06	040625770-0013	Station 10 Field Duplicate	12/4/06	3.64	Silica	NIOSH 7500 XRD	EMSL	12/5/06	< 1	No	No	
SILICA-ST11-12/04/06	040625770-0006	90 Trinity Place (roof level)	12/4/06	3.58	Silica	NIOSH 7500 XRD	EMSL	12/5/06	< 1	No	No	
SILICA-ST12-12/04/06	040625770-0007	110 Greenwich Street (roof level)	12/4/06	3.31	Silica	NIOSH 7500 XRD	EMSL	12/5/06	< 2	No	No	
SILICA-ST13-12/04/06	040625770-0008	Marriott Hotel, 38th Floor (roof level)	12/4/06	3.51	Silica	NIOSH 7500 XRD	EMSL	12/5/06	< 1	No	No	
SILICA-ST14-12/04/06	040625770-0009	West Face - South end at corner (scaffolding level)	12/4/06	3.52	Silica	NIOSH 7500 XRD	EMSL	12/5/06	< 1	No	No	
SILICA-ST15-12/04/06	040625770-0010	South Face - East end at corner (scaffolding level)	12/4/06	3.55	Silica	NIOSH 7500 XRD	EMSL	12/5/06	< 1	No	No	
SILICA-ST16-12/04/06	040625770-0011	East Face - North end at corner (scaffolding level)	12/4/06	3.54	Silica	NIOSH 7500 XRD	EMSL	12/5/06	< 1	No	No	
SILICA-ST17-12/04/06	040625770-0012	North Face - West end at corner (scaffolding level)	12/4/06	3.36	Silica	NIOSH 7500 XRD	EMSL	12/5/06	< 1	No	No	

Note:

1. Silica sample at Station 2 (Southeast Area [sidewalk bridge level]) on December 3, 2006 was not available for analysis on account of pump failure.