

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									10			
									10			
SILICA-ST1-12/08/06	040626156-0001	Southwest Area (sidewalk bridge level)	12/8/06	3.53	Silica	NIOSH 7500 XRD	EMSL	12/11/06	< 1	No	No	
SILICA-ST2-12/08/06	040626156-0002	Southeast Area (sidewalk bridge level)	12/8/06	3.52	Silica	NIOSH 7500 XRD	EMSL	12/11/06	< 1	No	No	
SILICA-ST4-12/08/06	040626156-0003	Northwest Area (street-level)	12/8/06	3.46	Silica	NIOSH 7500 XRD	EMSL	12/11/06	< 1	No	No	
SILICA-ST5-12/08/06	040626156-0004	Firehouse #10 (roof level)	12/8/06	3.58	Silica	NIOSH 7500 XRD	EMSL	12/11/06	< 6	No	No	
SILICA-ST10-12/08/06	040626156-0005	North Side Sidewalk Bridge	12/8/06	3.41	Silica	NIOSH 7500 XRD	EMSL	12/11/06	< 1	No	No	
SILICA-ST11-12/08/06	040626156-0006	90 Trinity Place (roof level)	12/8/06	3.64	Silica	NIOSH 7500 XRD	EMSL	12/11/06	< 1	No	No	
SILICA-ST12-12/08/06	040626156-0007	110 Greenwich Street (roof level)	12/8/06	3.52	Silica	NIOSH 7500 XRD	EMSL	12/11/06	< 1	No	No	
SILICA-ST13-12/08/06	040626156-0008	Marriott Hotel, 38th Floor (roof level)	12/8/06	3.49	Silica	NIOSH 7500 XRD	EMSL	12/11/06	< 1	No	No	
SILICA-ST14-12/08/06	040626156-0009	West Face - South end at corner (scaffolding level)	12/8/06	3.19	Silica	NIOSH 7500 XRD	EMSL	12/11/06	< 2	No	No	
SILICA-ST15-12/08/06	040626156-0010	South Face - East end at corner (scaffolding level)	12/8/06	3.16	Silica	NIOSH 7500 XRD	EMSL	12/11/06	< 2	No	No	
SILICA-ST16-12/08/06	040626156-0011	East Face - North end at corner (scaffolding level)	12/8/06	3.21	Silica	NIOSH 7500 XRD	EMSL	12/11/06	< 2	No	No	
SILICA-ST17-12/08/06	040626156-0012	North Face - West end at corner (scaffolding level)	12/8/06	3.16	Silica	NIOSH 7500 XRD	EMSL	12/11/06	< 6	No	No	