

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									10			
EPA Site Specific Trigger Levels									10			
SILICA-ST1-12/23/10	041029732-0001	Southwest Area (sidewalk bridge level)	12/23/10	3.64	Silica	NIOSH 7500 XRD	EMSL	12/28/10	< 1	No	No	
SILICA-ST2-12/23/10	041029732-0002	Southeast Area (sidewalk bridge level)	12/23/10	3.57	Silica	NIOSH 7500 XRD	EMSL	12/28/10	< 1	No	No	
SILICA-ST4-12/23/10	041029732-0003	Northwest Area (street-level)	12/23/10	3.69	Silica	NIOSH 7500 XRD	EMSL	12/28/10	< 1	No	No	
SILICA-ST5-12/23/10	041029732-0004	Firehouse #10 (roof level)	12/23/10	3.6	Silica	NIOSH 7500 XRD	EMSL	12/28/10	< 1	No	No	