

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target	Exceeds EPA	Comments
									10	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	
									10			
SILICA-ST1-12/30/05	040600053-0001	Southwest Area (sidewalk bridge level)	12/30/05	3.43	Silica	NIOSH 7500 XRD	EMSL	1/3/06	< 1	No	No	
SILICA-ST2-12/30/05	040600053-0002	Southeast Area (sidewalk bridge level)	12/30/05	3.39	Silica	NIOSH 7500 XRD	EMSL	1/3/06	< 1	No	No	
SILICA-ST4-12/30/05	040600053-0003	Northwest Area (street-level)	12/30/05	3.49	Silica	NIOSH 7500 XRD	EMSL	1/3/06	< 1	No	No	
SILICA-ST5-12/30/05	040600053-0004	Firehouse #10 (roof level)	12/30/05	3.57	Silica	NIOSH 7500 XRD	EMSL	1/3/06	< 1	No	No	
SILICA-ST10-12/30/05	040600053-0005	North Side Sidewalk Bridge	12/30/05	3.48	Silica	NIOSH 7500 XRD	EMSL	1/3/06	< 1	No	No	
SILICA-ST11-12/30/05	040600053-0006	90 Trinity Place (roof level)	12/30/05	3.67	Silica	NIOSH 7500 XRD	EMSL	1/3/06	< 1	No	No	
SILICA-ST12-12/30/05	040600053-0007	110 Greenwich Street (roof level)	12/30/05	3.8	Silica	NIOSH 7500 XRD	EMSL	1/3/06	< 1	No	No	
SILICA-ST13-12/30/05	040600053-0008	Marriott Hotel, 38th Floor (roof level)	12/30/05	3.5	Silica	NIOSH 7500 XRD	EMSL	1/3/06	< 1	No	No	
SILICA-ST14-12/30/05	040600053-0009	West Face - South end at corner (scaffolding level)	12/30/05	3.52	Silica	NIOSH 7500 XRD	EMSL	1/3/06	< 1	No	No	
SILICA-ST15-12/30/05	040600053-0010	South Face - East end at corner (scaffolding level)	12/30/05	3.46	Silica	NIOSH 7500 XRD	EMSL	1/3/06	< 1	No	No	
SILICA-ST16-12/30/05	040600053-0011	East Face - North end at corner (scaffolding level)	12/30/05	3.47	Silica	NIOSH 7500 XRD	EMSL	1/3/06	< 1	No	No	
SILICA-ST17-12/30/05	040600053-0012	North Face - West end at corner (scaffolding level)	12/30/05	3.54	Silica	NIOSH 7500 XRD	EMSL	1/3/06	< 1	No	No	